

This PDF is generated from: <https://www.ledact.co.za/Sun-22-Jun-2025-18536.html>

Title: Uninterruptible power supply exclamation mark appears

Generated on: 2026-06-01 06:12:42

Copyright (C) 2026 LEDACT SOLAR BATTERY. All rights reserved.

For the latest updates and more information, visit our website: <https://www.ledact.co.za>

---

We recently replaced our Eaton 9130 UPS + EBM with a new battery unit to solve an issue with alarm code #191 (battery-open cell voltage) & led triangle symbol flashing red / beeping. ...

The alarm will continue to beep until the UPS battery is drained or utility power is restored. The solution: Save your work and shutdown ...

CyberPower Uninterruptible Power Supply (UPS) also comes with various functions that would warn users about battery or power issues. It is recommended to ...

Web: <https://www.ledact.co.za>

